## North America Emission Control Area Fuel Oil Non-Availability Report
## ECA0100

## 1 2 3

## 
##(Include Double Pound for comments, not form fields)

##Report Form ID Ship Operator Name Vessel Name
ECA0100 Clipper Bulk Shipping Ltd. Clipper Valour

4 5 6 7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice
BS 9285407 12/30/2015 Rio Haina, Dominican Republic

Norfolk, USA

8

Rio Haina, Dominican Republic

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption NA

10

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA NA NA 1/2/2016

4		
14	15	16

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion 12:00 00.12

19

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? Norfolk, VA Y Y

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

NA NA

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? NA

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months? 1/14/2015 12:00 Y

27

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail 2 Mr. Lasse Vind Kronborg

bulk.opr.cph@clipper-group.com

Designated Corporate Official Phone Number +4549118162

Description of Actions to Achieve Compliance Last time charterers supplied LSMGO at Curacao with sulphur content 0.121%